



CABLE COUNTER LID:

Features 5 Digit Counter (4 digits for feet, 1 digit for inches)

Push Button Reset

Designed For Use With Rize Wire Rope

Fits most 5 gallon buckets

Lightweight

Organizing materials and tools for the jobsite requires some planning. Makes preparing for your hanging project alot simpler. Take an empty five gallon bucket, put a spool of wire rope in the bottom, put in some boxes of kwic-Locs and a cable cutter. Place the cable counter lid on top of the bucket and you are ready for the jobsite.

At the jobsite remove the Kwic-Locs boxes and the wire cutter, thread the wire rope through the measuring device and you are ready to hang. Just pull the wire rope to the length needed, cut it and reset the counter.

Item #	Code	Description	Weight	Packaging
R30390	RCDL	Lid Style English Cable Counter	4 lbs. boxed	1 per carton

